

Appendix B

Noise Monitoring Photographs



Looking south towards I-205 southbound lanes



Looking north towards property



Noise reading of 75 dBA



Looking southeast towards I-205 southbound lanes



Looking northwest towards paved area within property



Looking northeast towards property



Looking west along property edge


Noise Monitoring towards M1



Looking south from noise monitor



Looking west from noise monitor



Looking north towards monitor



Looking north of monitor



Looking south from monitor



Noise reading of 60 dB

Noise Monitor M2



Looking south towards monitor



Looking east towards the monitor



Noise reading of 59.5 dBA



Looking west towards monitor



Looking southeast towards monitor



Looking north towards monitor



Looking southwest towards monitor

Noise Monitor M4



Looking east towards monitor



Looking west towards monitor



Looking north towards monitor



Looking south towards monitor



Noise reading of 53.7 dBA

Noise Monitor IM5



Looking north towards monitor



Looking northwest towards monitor



Looking north towards monitor



Looking west towards monitor



Looking southeast toward monitor



Noise reading of 64.3 dBA



Looking north from monitor



Looking east towards monitor



Looking northeast from monitor



Looking south from monitor



Looking south from monitor



Noise reading of 50.2 dBA

Noise Monitor IM7



Looking west from monitor



Looking east from monitor



Looking southwest from monitor



Looking north from monitor



Noise reading of 55.9 dBA

Noise Monitor RM8



Looking west towards noise monitor



Looking southeast towards monitor



Noise reading of 52.1 dBA



Looking southwest towards monitor



Looking east towards monitor

Noise Monitor RM9



Looking northwest from monitor



Looking east from monitor



Looking south from monitor



Looking north from monitor



Looking southeast towards monitor



Looking northeast from monitor

Noise Monitor R11