




Top

Shattered PVC liner pipe scattered on the ground.



Top

Void in surface seal.



Top

Well dug with backhoe. When well was completed, driller back-filled pit without the benefit of a surface seal. Well casing did not meet standard.



Top

Well was sealed from 0-10 feet with bentonite. No seal was found below 10 feet.



Hole was cut in casing to place pitless adaptor and then glued back together.



Picture taken to show depth below the plastic tarp that I was able to run my tape down along the casing in the annular space after probing along side of the casing.